

This is a repository copy of A 28-year clinical and radiological follow-up of alumina ceramic-on-crosslinked polyethylene total hip arthroplasty: a follow-up report and analysis of the oxidation of a shelf-aged acetabular component.

White Rose Research Online URL for this paper: http://eprints.whiterose.ac.uk/122763/

Version: Accepted Version

Article:

Rajpura, A, Board, TN, Siney, PD et al. (4 more authors) (2017) A 28-year clinical and radiological follow-up of alumina ceramic-on-crosslinked polyethylene total hip arthroplasty: a follow-up report and analysis of the oxidation of a shelf-aged acetabular component. Bone and Joint Journal, 99-B (10). pp. 1286-1289. ISSN 2049-4394

https://doi.org/10.1302/0301-620X.99B10.BJJ-2017-0105.R1

© 2017 The British Editorial Society of Bone & Joint Surgery. This is an author produced version of a paper published in Bone and Joint Journal. Uploaded in accordance with the publisher's self-archiving policy.

Reuse

Items deposited in White Rose Research Online are protected by copyright, with all rights reserved unless indicated otherwise. They may be downloaded and/or printed for private study, or other acts as permitted by national copyright laws. The publisher or other rights holders may allow further reproduction and re-use of the full text version. This is indicated by the licence information on the White Rose Research Online record for the item.

Takedown

If you consider content in White Rose Research Online to be in breach of UK law, please notify us by emailing eprints@whiterose.ac.uk including the URL of the record and the reason for the withdrawal request.






Figure 1: Maximum penetration 0.41mm (0.4 to 0.41). Mean rate of penetration 0.0147mm/year (95% confidence interval 0.0142 to 0.0152).



Figure 2: A pelvic radiograph of a patient with a conventional Charnley low friction arthroplasty, metal on non-crosslinked polyethylene bearing, and an alumina-on-cross-linked polyethylene bearing on the contralateral side. There was significantly greater wear in the conventional bearing.