

This is a repository copy of *Data of the maximum solid solubility limits of binary systems of elements*.

White Rose Research Online URL for this paper: <u>https://eprints.whiterose.ac.uk/151712/</u>

Version: Published Version

Article:

Goodall, R. orcid.org/0000-0003-0720-9694 (2019) Data of the maximum solid solubility limits of binary systems of elements. Data in Brief, 26. 104515. ISSN 2352-3409

https://doi.org/10.1016/j.dib.2019.104515

Reuse

This article is distributed under the terms of the Creative Commons Attribution (CC BY) licence. This licence allows you to distribute, remix, tweak, and build upon the work, even commercially, as long as you credit the authors for the original work. More information and the full terms of the licence here: https://creativecommons.org/licenses/

Takedown

If you consider content in White Rose Research Online to be in breach of UK law, please notify us by emailing eprints@whiterose.ac.uk including the URL of the record and the reason for the withdrawal request.



eprints@whiterose.ac.uk https://eprints.whiterose.ac.uk/ Data in brief 26 (2019) 104515

Contents lists available at ScienceDirect

Data in brief

journal homepage: www.elsevier.com/locate/dib

Data Article

Data of the maximum solid solubility limits of binary systems of elements

R. Goodall

Department of Materials Science & Engineering, The University of Sheffield, United Kingdom

A R T I C L E I N F O

Article history: Received 9 July 2019 Received in revised form 5 September 2019 Accepted 6 September 2019 Available online 18 September 2019

Keywords: Periodic table of the elements Alloy design Solid solubility

ABSTRACT

This paper gives the available data for the maximum equilibrium solubility limits of each of the first 83 elements (H to Bi) of the periodic table in each of the others. This is expressed in the form of the maximum value of the equilibrium solid solubility for terminal solid solutions, expressed in atomic percentage (at%), occurring at any temperature where the room temperature phase of the pure element acting as the solvent is stable. The values thus represent the compatibility between different elements in the formation of alloys and similar combinations, and will be of use for research into fundamental solid state physics relating to elemental interactions, for the interpretation of phase structures in materials research and for the design of alloys and materials involving elemental mixing of the elements.

© 2019 The Author(s). Published by Elsevier Inc. This is an open access article under the CC BY license (http://creativecommons. org/licenses/by/4.0/).

1. Data

The data presented in this article are for the maximum equilibrium solubility limits of each of the first 83 elements (H to Bi) in each of the others. These are taken to be the maximum value of solid solubility for the terminal solid solutions, expressed in atomic percentage (at%), occurring at any temperature where the room temperature phase of the pure element acting as the solvent is stable. The values thus represent the compatibility between different elements in the formation of alloys and similar combinations, with higher values indicating a greater compatibility. A value of 100 at% indicates complete solid solubility, while a value of 0 at% indicates immiscibility in the solid state. The data are

https://doi.org/10.1016/j.dib.2019.104515







E-mail address: r.goodall@sheffield.ac.uk.

^{2352-3409/© 2019} The Author(s). Published by Elsevier Inc. This is an open access article under the CC BY license (http:// creativecommons.org/licenses/by/4.0/).

Specifications Table

Subject area	Chemistry
More specific subject area	Materials Science
Type of data	Table
How data was acquired	Survey and analysis of literature binary phase diagrams
Data format	Analyzed data, tabulated
Experimental factors	Each phase diagram was researched and assessed for detail and reliability
Experimental features	Where not already reported, diagrams were graphically analyzed for solubility data
Data source location	University of Sheffield, Sheffield, UK
Data accessibility	Raw data included in article, see Excel file in supplementary material

Value of the Data

- Many phase diagrams showing the equilibrium structures formed when mixing pairs of elements have been assessed, yet, while these are available individually, collected data across all systems, such as presented here, are not accessible without time consuming search.
- Solubility data for the solid phase allows interpretation and prediction of the behavior of elements combined into alloys. It
 is therefore of great use in physical metallurgy and alloy design, with application to the development of new materials
 including lightweight structural alloys, high temperature alloys, High Entropy Alloys, materials for hydrogen storage and
 novel functional materials such as permanent magnets, thermoelectric and magnetocaloric materials, as examples.
- The collation of this data displays the underlying trends arising from the role of the electronic structure in alloying (as displayed in the periodic table), and analysis of the data may reveal further detail and exceptions to established trends, the study of which may lead to refinement of theory in solid state physics.

presented in the form of a table, with each of the elements listed in order. Each row corresponds to a particular element acting as a solvent, and the columns show the solubility of each of the other elements as a solute in the system. Values have been given to the precision of the original measurements or predictive output on which the assessment is made. Data have been found for 3787 systems, and where no values are reported, the cell is left blank. The full data set is summarized below in 4 tables (see Tables 1–4) (split in this manner for legibility in the print version), each showing a quadrant of the overall matrix, while the complete table of the Raw data is included in Excel form for ease of data reuse in the Supplementary Material.

2. Experimental design, materials, and methods

The data presented have been obtained by an analysis of binary phase diagrams, obtained by a thorough survey of the literature. The majority of the diagrams used have been taken from major reference works on the subject [1-3], with the most recent report in each case taking precedence. Additional reports of mutually insoluble pairs and some more up to date data have been taken from the wider literature, with the full sources identified with the data (accessible with the Excel file containing the complete data). In each case, the reported data have been assessed to ensure a good standard of confidence is maintained, allowing phase diagrams derived from experimental investigation and those generated by thermodynamic calculation, but ensuring in either case that the reports are sufficiently detailed and supported by reference to wider literature. In some cases, maximum solubility limits are reported explicitly, and these are then taken to the accuracy at which they are reported. In other cases, where the diagrams only are shown they are graphically analyzed to determine the relevant values, which are given to the precision of other values provided in that study, or the dimensions of the relevant line, whichever is the lesser. All values are given in atomic percent, and where originally given in weight percent they are converted using the standard atomic masses of the elements concerned. Where no data have been found, the corresponding cells have been left blank.

E	lement	Ele	ment I	В																																				
A	1	Н	He Li	il	Be	В	С	Ν	0	FN	e Na	Mg	Al	Si	Р	S	Cl	Ar K	Ca	Sc	Ti	v	Cr	Mn	Fe	Со	Ni	Cu	Zn	Ga	Ge	As	Se	Br	Kr Rb	Sr	Y	Zr	Nb	Мо
H	ł												0																											
Н	łe																																							
L	.i	0		(0		0	0	0		0	76	0	0		0	0	0	2.2	0.1	0	0	0	0			0	0	0	0	0		0		0	0		0	0	0
В	Be	0	0			0	0		0		0	0	0	0				0	0		0	0	0.1		0.9	2.7	10	9.5	0	0	0			0	0	0	0	0	0	0
В	3			(0		0	0				0	0	2.5		0			0	2	0	0	2	4	0	0	0	0	0	0	4	0				0	0	0	0.5	0
C	2		0	(0	0					0		0	0					0	0	0	0	0	0	0	0	0	0			0	0	0		0	0	0	0	0	0
Ν	I						0		10)																														
C)							0																																
F	;																																							
Ν	le																																							
Ν	la	0	0	(0.1		0		0	0		0	0			0	0	1	0		0	0	0					0	0	0	0		0	0	0	0		0	0	0
Ν	Лg	11	1	8 (0	0	0	0	0		0		12	0	0			0	0.8	29	0.1	0	0	1.1	0	0	0	0	2	4	0				0	0	3.4	0.7	0.1	0
A	1	0	1-	4 (0	0	0	0	0		0	19		1.5	0	0		0	0	0.2	0.7	0	0	0.6	0	0	0	2.5	67	9	2.6	0	0			0	0	0	0	0
S	i	0	0	(0	2.6	0	0	0			0	0		2.5	0			0	1	0	0	0	0	0	0	0	0	0	0	100	3.5	0			0	0	0	0	0
Р)											0	0	0		0									0	0	0	0	0		0	35	0							0
S	;		0			0					0		0		0			0			0	0		0		0	0	0	0		0	0	12	0	0			0	0	0
C	21										0								0										0	0				100						
A	٨r																																							0
K	C C	0	0			0	0		0	0	4.7	0	0			0	0		0		0	0	0					0	0	0	0	0	0	0	100	0		0	0	0
C	Ca	0	1	0 (0	0	0	0	0	0	0	0	0	0			0	0		0	0	0		0.7	0		0	0	0	0	0			0	0	100	0			0
S	ic		0			0	2.6		11			28	10	0		0	0		1.4		11	0.5	0	0	0.5	0	1	1.1		0	2.7			0		1.6	100	100	0	0.5
Т	ï	7.5	0	(0	0	1.2	25	32	2	0	1.6	52	0.5	0	0		0	0	7.8		2	0.6	0.4	0	0.8	0	1.3	0	16	4.1		0.2		0	0	1	100	3	0.4
V	/	42	0		15	0	4.1	14	17	,	0	0	55	4.8		0		0	0	0.3	100		100	100	100	19	24	4.9	0	41	4.5		0		0	0	0	7.9	100	100
C	Cr	4	0	9	9.1	1	0	4.4	0		0	0	30	13	0	0	0	0		1.5	100	100		71	100	50	32	0	2	16	12	6	0		0		1	2.5	6.4	100
N	Лn		0			1	6.5	0.8	0			0	2	7.1	0	0			0	0	12	9	9		30	3	14	0.3	2	1	1.5	0	0			0	0	2		21
F	e	0	0	-	28	0	0.1	0.4	0		0	0	45	3.2	4.8	0		0	0	0.7	10	100	100	3		77	5.5	6.7	42	36	18	10	0		0	0	0.6	0.1	0.3	24
C	Co	0.5	2	6	12	0	4.5	0	0		0	0	17	19	0	0		0	8	0.6	14	2	44	20	2		35	20	2.8	1	18	2	0				0	0	0	0.9
N	Ji	0.9		-	24	0	2.9	0	0			0	21	16	0	0	0		0	1.6	15	43	50	100	100	100)	100	39	24	16	5	0			0	0	1.8	13	27
C	Cu	0.2	2	2	14	0.3	0		0		0	2.7	19	11	4	0	0	0	0	0.5	10	0.4	0.6	100	4.6	7.5	100		38	21	12	6.8	0			0	0	0	0.9	0
Z	'n	0	0.	.9 (0	0			0		0	0	2.9	0	0	0	0	0	0	0	0	0.2	0	1	0	0	0	2.8		2.4	0	0	0	0	0	0	0	0	0	0
G	Ja		0	(0	0	0				0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.5	0	0	0	0.8		0	0	0	0	0	0	0	0	0	0
G	je.		0	(0	0	0		0		0	0	1.1	100	0.2	0		0	0	0	2.3	0	0	0	0	1.5	0	0	0	1.1		0.2	0		0	0	0.3	0	0	0
A	ls		-			0	0				_	0	0	0	19	0		0			_	_	0	0	0.1	0	_	0	0	0	12		0	_	0	_			_	0
S	e		0			0	0				0		0	0	0	- 13		0			0	0	0	0	0	0	0	0	0	0	0	0		0	0	0			0	0

Maximum equilibrium solubility limits in binary systems involving the first 42 elements (H to Mo) as both the solvent and the solute. Data are shown as the solubility limit, in atomic percent (at %) of the element "B" in element "A".

(continued on next page)

Table 1 (continued)

Element	t Ele	ment	В																																							
A	Н	He	i	Be	В	С	Ν	0	F Ne	e Na	Mg	g Al	Si	Р	S	Cl	Ar	К	Ca	Sc	Ti	V	Cr	Mn	Fe	Со	Ni	Сι	1	Zn	Ga	Ge	As	Se	Br	Kr	Rb	Sr	Y	Zr	Nb	Мо
Br				0						0					0	100			0	0										0				0			0	0				0
Kr																																										
Rb	0	()	0		0		0	0	0	0				0	0		100	0		0	0	0							0	0	0	0	0	0			0		0	0	0
Sr	5	()	0	0	0		0		13	0	0	0			0		0	100	0	0	0		0	0		0	0		0.5	0	0		0	0		0		0			0
Y				0	0	7	3	15			20	0	0			0			0.5	100	0.9	0.3	0.7	0	1.6	0	0	0		0	0	1						6.4		1.8	0.1	0
Zr	5.2	()	0	1.5	0	23	31		0	0.4	8.3	0					0		100	100	2	1	0	0	5	0.2	2 0.	1	3.2	0.8	1					0		0		0.7	0
Nb	49	()	13	1.7	5.2	17	9		0	0.2	20	3.5		0			0		0	100	100	25		9.1	5.3	5	5.	6	0	19	11		0			0		0.1	100		100
Мо	0	0)	1	0.9	1.1	1	1	0 0	0	0	20	3	16	3	0	0	0	0	0.5	100	100	10	0 37	31	7.1	2.9	0 (0	15	5	0	0	0	0	0	0	0	9	100	

Maximum equilibrium solubility limits in binary systems involving the first 42 elements (H to Mo) as the solvent and elements 43 to 83 (Tc to Bi) as the solute. Data are shown as the solubility limit, in atomic percent (at.%) of the element "A".

Element l	Eler	ment	t B																																					
A	Гс	Ru	Rh	Pd	Ag	Cd	In	Sr	n Sb	Te	IX	Ke Cs	Ва	La	Ce	Pr	Nd	Pm	Sm	Eu	Gd	Tb	Dy	Но	Er	Tm	Yb	Lu	Hf	Та	W	Re	Os	Ir	Pt	Au	Hg	Tl	Pb	Bi
Н					_	-									_			_															_							
He																																								
Li		0	0	0	9	18	0	0	0	0		0	0	0	0	0	0	0	0										0	0				0	0	0		0	0	0
Be		0		5	0		0	0	0	0		0	0														0		0	0	0	0				0.3				0
B (0	0	0	0		0	0	0	0				0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.4	1	0	0		0	0	0	0	0	0
С		0	0	0				0	0			0	0	0	0	0	0			0	0	0	0	0	0		0	0	0	0	0			0	0				0	0
N																													0											
0																																								
F																																								
Ne				0	0	~	0	~	0	0	0	0																	0	0					~	0	0	1 1	0	~
INA Ma				0	0	0	0	0	10	0	0	0	5.7	0	0.1	0	0.0		0	0	4 5		10	E 4	60	6.2	1 2	0.0	0	0				0.2	0	0	12	1.1	0	1
NIg Al		0.5	0	0.2	0.0 22	0	0 19	<u>م</u>	40	0	0	0	0	0	0.1	0	0.8	0	0	0	4.5	0	4.8	5.4	0.9	0.5	1.2	0.0	0	0	0	0		0.2	0	0.1	1.2	10	0.1	1
Si		0.5	0	0	23	0	0	0	1 0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		0	0	0.1	0	0	0	0
P		0	0	0	0	0	U	0.	10	0			0		Ū	0	U		U		0	U	0	0	U	0	0	0	0	U	0	0	0	0	0	0		U	0	0
S		0	0	0	0	0	0	0	0	0.3	0	0				0			0	0			0				0				0		0	0	0	0	0	0	0	0
Cl					0		0				0	0	0																								0			0
Ar																																								
К					0	0	0	0	0	0	0	100	0 0																0	0						0	0	0	0	0
Ca				0	0	0	0	0	0		0	0	100	0 0	0		0.1		0	55	0	0.5	0		0	0.4	100	0.3							0		0	0	0	0
Sc		1	2	0	0		15	4.	5	0	0		2	15	12		100			0	100	100		100	100)			100	0.1	0	0		1	0	0			0	
Ti	1	0.1	0.1	1	4.7	'	10	11	12	0.9		0	0	1	1.2		1			0	6	1			0.1	0.1	0		100	3.6	0.2	8	20	15	2	1.7	0		4	0.5
V 4	44	25	18	38		0	5.5	5 16	6	0		0	0	0	0.6	0.1	0	0.1	0.1	0	0	0.1	0.1	0.1	0	0.1	0	0	4	100	100	65	37	22	11	33	0	3.4	ŀ	
Cr		32	20	1	~	0	0	2	5	0	0	0		2.5		0	1.5	0	0	0	0	1	0	3.7	0	0	0	0	2	4.3	100	50	30	11	6.8	3	0	~	0	0
Mn			1	3.7	0	0		2	1.5	0		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0.2	2	10	5.5	2	5	1	0	~	0	0	0
Fe		4	19	3.5	0	0	0.3	5 9.	25	1.5		0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0.7	0.8	15	8	3	8	100	I	0		0	0
CO Ni ²	20	21	100	20	0	0.3	0	11	0	0			0	0	0	0	0		0	00	0	0	0	0	0		0	0	0.5	4	10	100	14	100	100	100	0	25	0	0
	29.	0	100	100	1.4	: U 1 7 7	0	0	1 5 9	2 0	0	0	0	0	0	0	0	0	0	0.0	0	0	0	0	0	0	0	0	1	0	10	0	14	200 Q	100	100	5	2.5	0.1	0
7n (0	100	100	4.9	15	01	9. ⊨0	1 5.0	, 0	0	U	0	0	0	0	0	U	0	0	0	0	0	0	0	0	0	0	0.5	0	U	U		0	0	5 5	3	0.5	0	01
Ga		0		0	0	0	0.1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			0			0	0	0	0	0	0
Ge		0	0	0	0	0	0	1	10	0	0	Ő	0	2	U	0	1	0	0	0	0	õ	õ	õ	õ	õ	0	0	õ		0	0			õ	0	0	0	0	0
As		-	5	õ	0	õ	0	15	5 10	0 0	0	Ũ	0	-		Ũ	0		0	0	0	õ	õ	õ	0	õ	0	0	0	0	Ũ	U	0		0	0	Ũ	0	0	0
Se		0	0	0	0	0	ō	0	0	10	0 0	0	0	0	0	0	-		-	-	-	-	-	-	0	0	0	-		0			0		-	0	0	0	0	0
					•	0	0	0	0	100					-	~									0	0	0										-		-	

сī

R. Goodall / Data in brief 26 (2019) 104515

Table 2	(continued)
---------	------------	---

Elemen	t Elem	ent	В																																					
A	Tc R	u	Rh	Pd	Ag	Cd	In	Sn	Sb	Те	IX	Ke Cs	Ва	La	Ce	Pr	Nd	Pm S	Sm E	u Go	Tb	Dy	ιH	lo I	Er	Tm `	/b	Lu	Hf	Та	W	Re	Os	Ir	Pt	Au	Hg	; Tl	Pb	Bi
Kr																																								
Rb					0	0	0	0	0	0	0	100	0 (0	0						0	0	0	0	0
Sr					0	0	0	0	0	0	0	0	22				0.3																		0	0	0	0	0	0
Y	0			0	0		8	1.7	1.7		0		7.9	100)		100	1	00	10	0 10	0 10	01	00	100	()	100	1	0		0	0	0	0				2	0
Zr	0	.6	0	1	1.3	18	10	6.5	0.8	0		0		0	2.8		3.4		0	3	4.	1 7	3	8.7 2	28	() 4	4.9	100	0.7	4	1.5	1.5	1	1.5	2	0		5	4
Nb	4	0	21	36			0	11	20	0	0	0		0.1	0			0	0.1 0					(0	() (0	100	100	100	46	19	12	12	36	0	0		
Мо	49 3	3	20	6	0	0	0.1	0	0	0	0 0	0 (0	0.1	0.3	0.3	0.3	0.3 () 0	1	0.	7 0.6	5 0).6 (0.5	0.5 () 4	4	23	100	100	38	18	16	15	0.4	0	0	0	0

Elemen	t Ele	mer	nt B																																							
A	Н	He	Li	Be	В	С	Ν	0	ΓI	Ne N	a M	lg /	41	Si	Р	S	Cl /	٩r	K	Ca	Sc	Ti	V	Cr	Mn	Fe	Со	Ni	Cu	Zn	Ga	Ge	As	Se	Br	Kr	Rb	Sr	Y	Zr	Nb	Мо
Тс					0	7.2																14	8					46	0	0											_	25
Ru			0	1	1.8	3						4	1	4.5	0	0					1.5	14	30	52	51	77	100	49	0	0	0			0					0	2	29	52
Rh			0		0	1.5						()	2.3	0	0					11	14	20	32		100	100	100	100)		0		0						8	17	15
Pd	0.1		4.4	1.1	18	8				2	25	5 1	19	0	0	0	0			0	15	15	58	50	28	100	100	100	100	20	11	3	0	1.5					13	14	30	46
Ag		0	61	0.4	0	0		0		0	24	4 2	20	0	0	0.1	0 ()	0	0	10	4	1	0	55	0	0.8	0.3	14	40	19	9.6	8.8	0	0	0	0	0	1.6	5.3		0.2
Cd			30		0			0		0	10	00 ()	0	0	0	0		0	0	0	0	0	0	0	0		0	0.2	4.4	0	0	0	0			0	0	0	0		0
In			1.6	0	0					2	95	()	0	0	0	0		0	0	0	0	0		0	0	0	0	0	2	2.3	0	0	0	0		0	0	0	0	0	0
Sn			0	0	0	0		0	0	0	0	()	0	0	0	0		0	0.4	0	0	0	0	0	0	0	0	0	0	6.5	0	0	0	0		0	0	0	0	0	0
Sb			0	0	0	0		0		0	0	()	0	0.1	0			0	0		0		0	0	0	0	0	0	0	0	6.2	100	0			0	0	0	0	0	0
Te			0	0				0		0	0	()	0		14	0		0		0	0	0	0	0	0	0	0	0	0	0	0	0	100	0		0	0	0	0	0	0
I										0		()			0	0		0	0	0			0					0	0	0	0		0	0		0	0	0		0	0
Xe																																										
Cs	0		0	0		0		0	0	0	0					0	0		100	0		0	0	0					0		0	0		0			100	0		0	0	0
Ba	58		0	0	0	0		0		1	2 0	()	0	0		0		0	100	0	0	0		1.2	0		0	0	0	0	0		0	0		0	100	0.2			0
La	1.4		0		0	4.5					1.	1 ()			0	0			0	11	0	1.4		0	0	0	0	0	0	0	0		0	0				100	0	0	0
Ce			0		0	4.5	3				8.	1 ()	0		0				0.3	17	0	0		5.2	0	0	0	0	0	0	0		0	0							0
Pr			0		0	4.5		0			9.	2 3	3	0	0.3	0	0					3	0	0		0	0	0	0	1.5	4	0		0	0							0
Nd	12		0		0	0		0			8.	9 2	2.1	0						3.5	100	0	0	3	2.5	0	0	0	0	1		0.5	1					5.8	100	1.5		0
Pm			0		0							()										0.2	0	0	0			0		0											0
Sm			0		0				0		3	()	0		0				0.2			0	0	0	0.5	0	0	0	0	0	0	0						100		0.1	0
Eu					0	0		0			0	()			0				100	0	0	0	0	0	0		0	0	0	0	0	0							0	0	0
Gd					0	0					14	4 ().5	0			0			0.2	100	0.3	0	0	0	0	0	0	0		0	0		0					100	3.4		0
Tb					0	0		0			12	2 ()	0						9	100		0.2	3	0	0	0		0		0	0	1						100			0
Dy					0	0					13	3 ()	0		0	0			0.2			0.3	0	0	0	0	0	0		0	0	1						100	1.5		0.6
Ho					0	0					15	5 ()	0			0				100		0.5	2	0	0	0	0	0	0	0	0	1						100			0.6
Er	40				0	0		0			6.	9 ()	0			0			0.2	100	3	0	0	0	0	0	0	0	0	0	0	1	0					100	42	1	0.5
Tm					0						13	3 ()	0		0	0			6.4		1	0.4	0	0	0			0	0	0	0	1	0								0.7
Yb					0	0			0		0	().6	0		0	0			100		0	0	0	0	0	0	0	0	0	0	0	0	0					0	0	0	0
Lu					0	0					12	2 ()	0						6.4			0.5	0	0	0	0		0	0	0	0	1						100		0.5	4
Hf	9		0	0	1.5	14	29	25		0	0	2	27	0					0		100	100	3.4	1.7	2		3	0.9	0.3								0		4	100	5.2	2
Та	34		0	0	2	7	11	5.7		0		6	5.9	10								100	100	27		8.5	21	21	0				0	0	0		0		0	100	100	100
W				5.8	8 0	1	0	0				1	15	3		0						100	100	100) 12	4	3	0.3	0			2.5							0	3.6	100	100
Re				10	0	11						2	2.8	9.2							6	3	13	23		0	100	17	0		0	0							0	4	4	13
Os					0	2									0							21	48	65		75	100	12					0	0					0	8	27	52
Ir			0			3.1						2	20	0	0						11	11	19	27		100	100	100	6.4										0	9	15	23

Maximum equilibrium solubility limits in binary systems involving elements 43 to 83 (Tc to Bi) as the solvent and the first 42 elements (H to Mo) as the solute. Data are shown as the solubility limit, in atomic percent (at.%) of the element "A".

7

(continued on next page)

Tab	le 3	(continued)
-----	------	------------	---

Elemen	t Ele	ement B																																					
A	Н	He Li	В	e B	С	Ν	0	FΝ	e Na	a M	g /	41	Si	Р	S	Cl Ai	K	Ca	Sc	Ti	V	Cr	Mr	Fe	Со	Ni	Cu	Zn	Ga	Ge	As	Se	Br ŀ	Kr Rb	Sr	Υ	Zr	Nb	Мо
Pt			0	0	2.5				1		1	6	0.7	0	0			0		11	57	69	38	100	100	100	100	22	14	6.7	0				0	0	13	20	44
Au	0	17	0.	25	0.1	0			0	0	1	3	0	0	0	0	0	0	9.4	11	61	47	31	74	23	100	100	35	12	3	0	0	0	0	0	2	8.1	57	1.3
Hg		0		0	0				0	0	()			0	0	0	0		0	0	0	0	0	0	0	0	0.3	0	0		0	0	0	0	0	0.3	0	0
Tl		1.4	1	0					27	2.	1 ()	0	0	0	0	4	2			0		0			0	0	0	0	0	0	0			4.5	0		0	0
Pb		2.9)	0	0		0		20	5.	7 2	2.3	0		0	0	0	0	0	0		0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		0
Bi		0	0	0	0		0		0	0	()	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1.6	0	0	0.6	0	0	0	0	0	0	0	0

Maximum equilibrium solubility limits in binary systems involving elements 43 to 83 (Tc to Bi) as both the solvent and the solute. Data are shown as the solubility limit, in atomic percent (at.%) of the element "B" in element "A".

Elemen	t Elei	nent	В																																				
A	Tc	Ru	Rh	Pd	Ag	Cd	In	Sn	Sb	Те	ΙХ	le Cs	Ва	La	Ce	Pr	Nd	Pm	Sm	Eu	Gd	Tb	Dy	Но	Er	Tm	Yb	Lu	Hf	Та	W	Re	Os	Ir	Pt	Au	Hg T	'l F	Pb Bi
Тс						_	_	_		0							_														12	100							
Ru			60	8				0	0	0		2		1.5	2		0		0		0	0	0		0		0	2	5	28	48	100	100	49	21	0	0		
Rh		35		100	10			15	6.5	1				0	0		0	0	0	0	0		0		0		0	1	5	18	19	12	55	100	100	0.3	0	0)
Pd		21	100		100	26	19	17	17	16			0		13	9	3		10		12	12	12	12	13		13	13	23	18	22	16	2.9	100	100	100	14	1	17
Ag		0	0	100		42	21	12	7.2	0	0		0	0	0.1	0.1	0.3	0	1	0	0.7	1.1	1.3	1.4	3.1	4.6	1.9	5.8			0	0	0	0	40	100	37 7	.8 2	2.8 2.6
Cd				0	7		1.4	1 0.2	0	0	0	0	0	0	0	0	0	0	0	0	0						0								0	4	25 0) (0 (
In			0	0	0	6		12	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0		0				0	0	0	4.5 3	1	8.2
Sn		0	0	0	0	1.1	0		0	0	0	0	0	0	0	0	0		0	0	0	0	0	0	0	0	0	0	0	0		0			0	0	1 0) () 13
Sb		0	0	0	0	0	0	12		1.3		0		0	0	0	0		0		0	0	0	0	0	0	0.9	0			0	0		0	0	0	0 0	2	2 100
Te	0	0	0	0	0	0	0	0	0		0	0	0	0	0	0	0		0	0	0		0	0	0	0	0		0	0	0	0	0	0	0	0	0 0) (0 (
I						0	0	0		0		0	0								0	0		0	0												0 0)	0
Xe																																							
Cs						0	0	0	0	0	0		0			0													0	0						0	0 0) (0 (
Ba				0	0	0	0			0	0	0		0.2		0	0	0	0	100)						100								0		0 0) ()
La		0	0		0	0	0	0	0	0			0		100	100	10	0 100	0 100)	100		21				0			0	0	0		0	0	0	0 0) (0 0
Ce		0	0	0	0		0	0	0	0	0			100		70	10	0 100) 2	4.4	3								0	0	0			0	0	0	0 0) (0 0
Pr			~	0	1.3		5.6	5 3.5	52	0		0	0	100	100)	10	0 100)		100		100				~ ~		0	0	0	0	0.2	0	0.1	1	0.9 2	.5 2	2.2 0
Nd		0	0		0.9	0	5	2	0	0			0	100	100	100		100	0 100)	100		100		100		2.2			0	0			0	1	0	3	2	2.5 0
Pm			~			~	5	~		~			0	100	100	100	10	J			100		100					_								0	4		
Sm		0	0	0.7	0	0	0	0	0	0			0	7	20		13				40	19	15	13		9		7		0	0			0	0	0.2		()
Eu		~	0	0	0	0	0	0		0	~			5	0	100						100	100	0	100	100	100	100	0	0	0	~			0	0	-)
Ga		0	0	3./	0	5	/	0	4	0	0			100	30	100	10	0 100	100)	100	100	100	100	100	100	19	100		0	0	0		0	0	0	· /	.2 1	
1D Du		0	0	0	0		9	0	0	0	0			62		100	10	0 100	100)	100	100	100	100	100	100		100		0	0	I		0	0	0	0		
Dy		0	0	0	0		0	2	0	0	0			62		100	10	5 100	100	,	100	100	100	100	100	100		100		0	0			0	0	0	5		1
П0 Er		0	r	0	0		0 7	2.3	00	0	0						10	n	100	0	100	100	100	100	100	100		100	25	0	0	0		0	0	0	0 6		1
EI Tro		0	2	0	0		10	1.4	25	0	0						10	J	100	`	100	100	100	100	100	100		100	2.5	0	0	0		0	0	0	0 0		0
Vh		0	0	0	0	14	10	0	0	0			10	0			17		100	,	14	100	100	0	100			0	0	0	0		0	0	0	0	0 6	; c	1
In		2	0	0	0	1.7	FU	0	3	U			10	U			1.7		100	•	100	100		100	100	100	15	0	0	0	0		0	0	0	0	0 0) S
Hf		2	з	1	0			14	0	0		0			05	0			100	,	100	100	100	100	75	100	0			51	0	0.8	1	14	0	5	0		.0
Та		2 49	16	25	0		0	9	U	0		0			0.5	U				0		0	100		7.5	0	0	0	100	5.1	100	47	78	73	9	20	С С		0
W	55	23	6	5			U	5	0	0		U		0	0	0	0		0	0	0	0	0		0	0	0	0	75	100	100	37	19	10	47	0	0		0
Re	100	100	24	5				0	0	0				õ	Ū	U	U		0	Ū	0	1	0		0	0	0	0	11	4	20	5,	100	44	44	0	0		0
Os	100	100	30	5.2	0			U	Ū	0				0		0					0	•			0		0		13	19	54	100	100	38		0	0		0
Ir		45	100	100	0		0		0	0				0	0	0	0	0	0		0	0	0	0	0	0	0	0	10	16	19	36	44		100	2	0		0
				0	-		-		-	-				-	-	-	-	-	-		-	-	-	-	-	-	-	-								-	-		-

(continued on next page)

Table 4 (continued)	
---------------------	--

Elemen	t Ele	ment	В																																			
A	Тс	Ru	Rh	Pd	Ag	Cd	In	Sn	Sb	Te	I Xe	Cs_Ba	La	Ce	Pr	Nd	Pm	Sm	Eu	Gd	Tb	Dy	Но	Er	Tm	Yb	Lu	Hf	Та	W	Re	Os	Ir	Pt	Au	Hg T	l Pb	b Bi
Pt		74	100) 100	13		13	11	11	3		0	0	0		1		0	0	0.7	0	0	0	0	0	1	0		19	63	48	25	100		100	0	0	0
Au	0	0	1.6	100	100	33	14	7.3	0	0.2		0	0	0	0.1	0	0	0.3	0	0.7	1.5	2.3	3.9	5.7	0	7.1	7.7	5	35	0	0	0	0.1	100)	20 1	0.	1 0.1
Hg		0	0	0	0	3.5	19	0	0	0	0	0 0	0		0	0		0		0	0	0	0	0		0		0			0	0	0	0	0	0	0	0
Tl				0	0	4	13	3	3	0	0	0 1.7	70	0	0	0	0	0		0	0	0	0	0	0	0	0		0					0	0	2.5	4.	31
Pb			0	0	0.2	5.9	71	28	7	0		0 0	0.1	0	0	0		2	0	0	0	0				0	0			0				0	0.2	25 9	0	25
Bi		0	0	0	0	0	0	3	100	0	0	0 0	0	0	0	0		0		0	0	0	0	0	0	0	0.1	0	0	0	0	0	0	0	0	0 0	0	

Acknowledgments

The author would like to acknowledge a Fellowship supported by the Royal Academy of Engineering under the RAEng/Leverhulme Trust Senior Research Fellowships scheme.

Conflict of interest

The authors declare that they have no known competing financial interests or personal relationships that could have appeared to influence the work reported in this paper.

Appendix A. Supplementary data

Supplementary data to this article can be found online at https://doi.org/10.1016/j.dib.2019.104515.

References

- [1] Hiroaki Okamoto, Mark E. Schlesinger, Erik M. Mueller (Eds.), ASM Handbook, vol. 3, Alloy Phase Diagrams, ASM, Ohio, 2016.
- [2] T.B. Massalski, J.L. Murray, L.H. Bennett, H. Baker (Eds.), Binary Alloy Phase Diagrams, ASM, Ohio, 1986.
- [3] H. Okamoto, Desk Handbook; Phase Diagrams for Binary Alloys, ASM, Ohio, 2000.