

This is a repository copy of *An empirical investigation on the correlation between solar cell cracks and hotspots*.

White Rose Research Online URL for this paper:

<https://eprints.whiterose.ac.uk/181665/>

Version: Published Version

Article:

Dhimish, Mahmoud and Lazaridis, Pavlos I. (2021) An empirical investigation on the correlation between solar cell cracks and hotspots. Scientific Reports. ISSN 2045-2322

<https://doi.org/10.1038/s41598-021-03498-z>

Reuse

This article is distributed under the terms of the Creative Commons Attribution (CC BY) licence. This licence allows you to distribute, remix, tweak, and build upon the work, even commercially, as long as you credit the authors for the original work. More information and the full terms of the licence here:

<https://creativecommons.org/licenses/>

Takedown

If you consider content in White Rose Research Online to be in breach of UK law, please notify us by emailing eprints@whiterose.ac.uk including the URL of the record and the reason for the withdrawal request.



OPEN

An empirical investigation on the correlation between solar cell cracks and hotspots

Mahmoud Dhimish¹✉ & Pavlos I. Lazaridis²

In recent years, solar cell cracks have been a topic of interest to industry because of their impact on performance deterioration. Therefore, in this work, we investigate the correlation of four crack modes and their effects on the temperature of the solar cell, well known as hotspot. We divided the crack modes to crack free (mode 1), micro-crack (mode 2), shaded area (mode 3), and breakdown (mode 4). Using a dataset of 12 different solar cell samples, we have found that there are no hotspots detected for a solar cell affected by modes 1 or 2. However, we discovered that the solar cell is likely to have hotspots if affected by crack mode 3 or 4, with an expected increase in the temperature from 25°C to 100°C. Additionally, we have noticed that an increase in the shading ratio in solar cells can cause severe hotspots. For this reason, we observed that the worst-case scenario for a hotspot to develop is at shading ratios of 40% to 60%, with an identified increase in the cell temperature from 25°C to 105°C.

To aid the transition to green energy, there has been a considerable demand to combine more photovoltaic (PV) systems into the electric grid to support the growth of renewable energy sources. As such, PV reliability and durability receives great interest from the industry as there are currently various mismatching conditions affecting these installations^{1–3}. One of the challenges in today's PV modules is the well-known phenomenon called hotspots⁴. A hotspot is a localized heat source that can be present in part(s) of the PV module, leading to locally increased temperature in the solar cells. An example of a PV module affected by hotspots is shown in Fig. 1.

There are currently undergoing investigations on how PV hotspots occur in PV modules. Some researchers suggest that hotspots are present due to the rapid change in the night-to-day temperature⁵, particularly in deserts and coastal areas⁶. However, there is no complete demonstration of how hotspots develop, especially for new PV modules that are not affected by any means of cracks or physical damages. For example, Dhimish et al.⁷ observed that hotspots are likely to develop in cracked solar cells, and they show that a complete hotspot string within a PV module could lead to a 25% loss in output power. At the same time, the temperature could also increase by up to 65°C. In this study, the examined PV sub-strings were operated under indoors conditions.

There were some attempts to explain how cracks could lead to hotspots^{8,9}, yet this has not been fully reported in the literature. It is worth noting here that cracks are generally presented as one mode; however, some recent studies^{10–12}, have explained that cracks could be classified into different modes, including micro-crack and breakdown regions. This topic has been of great interest to the industry because solar cell cracks are proven to affect the output power yield and several studies evidence^{13,14} that this could lead to a significant drop in the solar cells' other electrical parameters, such as the open-circuit voltage, short circuit current, and the fill factor. The problem occurs when the crack area is electrically disconnected, limiting the maximum output current generation and, as a result, leading to an electrical mismatching condition.

The mitigation of solar cell cracks has not been yet discovered. However, several studies explain how to mitigate solar cell hotspots. The old-fashioned approach^{15,16} is to connect the PV sub-strings in parallel with a bypass diode. This technique allows the current to have a different path and allows the unshaded solar cells to generate more current. Recent techniques such as^{17–20} have proposed the same principle, although adopting a metal–oxide–semiconductor field-effect transistor (MOSFET) in series with the cracked/hotspot PV string. The technique allows the MOSFET to regulate the current. It was confirmed that these techniques improve the output power of affected PV modules. However, their main limitations are, (i) the requirement of additional power supply to control the MOSFET switching, (ii) the internal power electronics circuit dissipating power,

¹Department of Electronic Engineering, University of York, Heslington YO10 5DD, York, UK. ²Department of Engineering and Technology, University of Huddersfield, Huddersfield HD1 3DH, UK. ✉email: Mahmoud.dhimish@york.ac.uk




Figure 1. The physical and thermal image of a PV module is affected by hotspots; the thermal image is captured using a FLIR i5 thermal imaging camera, which has a thermal sensitivity of $\pm 1^\circ\text{C}$.




Figure 2. Detection methods used in this study.

and (iii) these techniques are complicated to configure with many solar cells; customarily, they connect along with full-scale PV modules rather than individual solar cells.

The main contributions of this paper are, (i) an investigation of the correlation of solar cell crack modes and the presence of hotspots; four different crack modes were identified based on captured electroluminescent (EL) images of the examined solar cells, (ii) a mapping of the correlation between the cracks modes based on empirical results of measured output power, and (iii) a better understanding of the relationship between the shading ratio in the original EL image and the presence of hotspots.

Materials and methods

Test samples. The examined solar cell samples have been dismantled from 22 series-connected PV modules operating in the field for five years, and all were in the same PV site located near Leeds city in the UK. The PV manufacturer carefully managed this process to ensure no extra cracking or further damage was induced to the cells. The solar cells are polycrystalline silicon (poly-Si) with a peak power of 3.66 W at standard test conditions (STC), where the solar irradiance is 1000 W/m^2 and cell temperature 25°C . Each cell has a 3.2 mm glass superstrate, an ethylene-vinyl acetate (EVA) encapsulant²¹, and AAA backsheet substrate²².

Scientific methods and techniques. The scientific methods/techniques to study the solar cell samples are summarised in Fig. 2. EL imaging is used to identify the cracks and defects in the cells^{23,24}, whereas thermal imaging is applied to determine whether the cell sample has a hotspot. The solar cell samples have been tested under the sun simulator at STC conditions, where the cell was illuminated at 1000 W/m^2 light intensity. The temperature of the cell was measured from the rear (non-illuminated) side using a thermal camera. For every sample, the temperature was left to develop for 10 min before measurement. This allowed sufficient time for the hotspots, if any, to reach a steady state with minimal fluctuations observed. And finally, to observe any micro-level fractures and defects in the cells, we have used scanning electron microscopy (SEM).

Electroluminescent, thermal imaging, solar simulator, and SEM. The EL images of the solar cell samples are taken using the EL camera shown in Fig. 3a. The camera comprises a digital single-lens reflex with a high resolution of $6\text{ k} \times 4\text{ k}$ pixels. The infrared cut-off filter is removed and calibrated to allow sensitivity to the electroluminescence picture with a peak wavelength of 1150 nm . The camera has an adjustable lens of $18\text{--}55\text{ mm}$. The accuracy of the EL image depends on the distance between the EL camera and the solar cell. In our experiment, the distance was 2.4 m , which produces the highest quality EL images.

To capture the thermal image of the solar cells, a FLIR E8-XT thermal imaging camera is used (Fig. 3b). The thermal camera has a thermal resolution of 320×240 -pixel and 0.05°C thermal sensitivity. The camera was placed 2.4 m apart from the solar cells to detect the entire area of the inspected cells.

Finally, to investigate the performance of the solar cells under varied solar irradiance ($0\text{--}1000\text{ W/m}^2$), a steady-state solar simulator is used, presented in Fig. 3c. The solar simulator is a class A + spectral match, IEC60904-9, with a $\pm 2\%$ illumination sensitivity. In addition, we have used the Quanta FEC250 SEM, Fig. 3d,




Figure 3. Experimental setup (a) EL imaging camera, (b) thermal camera, (c) solar simulator, and (d) scanning electron microscope.




Figure 4. EL image of the examined solar cell samples (a) mode 1, (b) mode 2, (c) mode 3, and (d) mode 4.

to inspect the microstructure of the examined solar cells. The SEM has an adjustable magnification of up to 2,000,000x, and the resolution of the digital output image can be as high as 4096×3536 .

Results

EL imaging. Every solar cell was subjected to EL imaging to inspect the fracture and the crack mode. In this study, we have investigated four different modes: (i) crack free (mode 1), (ii) micro-crack (mode 2), (iii) shade area (mode 3), and (iv) breakdown (mode 4). For every mode, three different solar cell samples were selected, all presented in Fig. 4. Here the cracks were classified into four different modes. In contrast, in previous research^{25,26}, solar cell cracks were distinguished by either a singular crack mode, named micro-crack or μ crack. We find our classification is significant because not every crack mode can lead to hotspots or a substantial drop in the output power.




Figure 5. Thermal image of the examined solar cell samples under STC condition (a) mode 1, (b) mode 2, (c) mode 3, and (d) mode 4.

Cracks formed in the solar cells for various reasons, including defective manual soldering, improper installation of the PV modules in the PV site, transportation, and unavoidable materials defects. The cracks themselves cannot be mitigated/alleviated, and they are likely to grow as the solar cells continue to be exposed to solar irradiance and to fluctuations in temperature.

Thermal performance of the tested solar cell samples. The results of the thermal testing are shown in Fig. 5. According to Figs. 5a,b a uniform distribution of the heat across the solar cell surface was detected. Accordingly, the temperature is approximately at the standard testing condition, 25°C. It is noticed that no hotspots are exposed to the solar cell samples with crack-free (mode 1) and micro-cracks (mode 2). Furthermore, for crack modes 1 and 2, there was no increase in the cell's temperature, which confirms that crack-free or micro-cracks do not change the temperature of the cells and are unlikely to develop a hotspot.

In contradiction, if we consider Fig. 5c, mode 3, the shade in the cells causes no increase in the temperature, labelled in dashed circles. The shade will create an uneven distribution of the current flow in the busbars; this would generate stress in the cell and then cause an increase in the temperature. We can observe that the samples are affected by the rise to the surface temperature up to 77.6°C. Hence, if these samples were under field operation, hotspots would be expected. We yet do not fully understand the correlation between the shading ratio in the original EL image and the presence of hotspots; this case will be detailed later in the article.




Figure 6. Measured power vs irradiance of the examined solar cells.




Figure 7. Normal distribution function applied for all measured data points.

According to mode 4, Fig. 5d, the breakdown regions in the solar cells have no increase in the temperature, labelled in dashed circles. This is explained by the fact that there is no contact in the inner and outer layers of the cells. Hence, no photo illumination is observed. In contrast, the cells are now being impacted by an increase in the surface temperature (of up to 93.3°C) due to these breakdown regions. The same explanation is valid as in crack mode 3, where breakdown regions affect parts of the solar cells, which would create an uneven distribution of the current flow in the busbars, leading to this significant increase in the cell surface temperature. A similar observation was made in the recent study by Akram *et al.*²⁷, where they discovered that a hotspot could lead to an increase in the cell surface temperature of up to 110°C .

The results of the development of the hotspots in crack modes 3 and 4 lead us to explain why in some commercial PV systems, some modules do not develop hotspots even though they appear to have snail trails²⁸ or cracks. Accordingly, for a solar cell to exhibit severe hotspots, it certainly depends on the cracking mode and how long this crack has been settled in the solar cell sample.

Output power measurements. Using the solar simulator, the examined samples were subjected to illumination over the spectrum range from 100 to 1000 W/m^2 . The results of each mode are given in Fig. 6, including the linear regression. Modes 1 and 2 have a similar output power pattern, and their average measured power is 1.87 W and 1.81 W, respectively. On the other hand, a significant drop in the measured power for modes 3 and 4 is observed, averaged at 1.41 W and 1.18 W, respectively.

We show here that for modes 1 and 2, there is an insignificant change for the maximum-to-minimum output power across the range of the solar spectrum. However, for modes 3 and 4, a considerable difference in the measured power, particularly at high solar irradiance ($> 500\text{ W/m}^2$).

Additionally, we summarise that the measured output power of the solar cell samples follows a normal distribution as presented in Fig. 7. However, a lower standard deviation (StDev) for modes 3 and 4 indicates that the output measure power tends to be close to the mean value. This result suggests that a significant drop in the




Figure 8. (a) Correlogram graph for the different solar cell crack modes investigated in this work, and (b) Solar irradiance vs output power of each crack mode.

solar cells' output power is likely to be noticed if the EL image exhibits a shaded area or breakdown regions. Finally, please note that for Fig. 7, the y-axis (density) represents the percentage of the observations in the dataset.

A correlogram is a chart of correlation statistics between different samples data; it presents the correlation between each class in the data obtained from various experiments. In our case, we have adopted the correlogram to explain the correlation between the different solar cells cracks modes. This way, we can better understand how each mode correlates with the other.

Taking the measurements of the output power of each solar cell cracks mode, the correlogram is compiled and presented in Fig. 8a. In this figure, we notice that even though modes 3 and 4 looks similar in the original captured EL images, both have the least correlation, 0.86 or 86%. This outcome is found due to the nature of the cells' breakdown regions (mode 4). Therefore, they are likely to exhibit an unpredictable power loss and increase the cell's temperature with multiple levels, as small as 50°C to 93.3°C. On the contrary, the solar cells affected by crack mode 3 are likely to have a drop in the output power with steady fluctuations, as analysed in Fig. 8b, compared with mode 4.

Finally, and as expected, the highest correlation is marked for modes 1 and 2 at 99%. Because both crack modes exhibit the same output power losses, and they show no impact on the cell's temperature.

Shading ratio vs hotspots development. So far, we have evidence that solar cells affected by modes 3 and 4 are expected to have hotspots. Therefore, we have further investigated the correlation between the shade ratio in mode 3 and the presence of hotspots. The outcome of this experiment is presented in Fig. 9.

The progressive range of shade, including 25%, 40%, 60%, 80%, and 100%, is examined. If the solar cell is affected by 25% shading ratio, a maximum increase in the cell's temperature of approximately 75°C is detected. Progressively, if the solar cell is affected by a greater shading ratio, 40% or 60%, the hotspot area has a significant




Figure 9. Progressive shading of a solar cell affected by mode 3 crack; the samples were subjected to illumination under STC conditions.

increase in temperature, equivalent to 105°C. Therefore, a hotspot is likely to develop for these three shading ratios.

For the last two shading ratios, when the solar cell is affected by 80% or 100%, no hotspot in the cell area is witnessed. The hotspot disappears due to the absence of the photo-generated current. The remaining dark current flows within the cell for insignificant cell heating and an average temperature approximately at the experimental condition, 25°C. Thus, the worst-case scenario for the hotspot to develop occurs at the shading ratios of 40% to 60%, with an expected increase in the cell temperature from 25°C to 105°C.

Therefore, we have scanned the solar cell affected by a 60% shading ratio under SEM. This experiment was performed after the cell has been under illumination (1000 W/m²) for three continuous hours. The SME image of the hotspot busbar is presented in Fig. 10 under 200 and 1000 magnification. Here we can observe that the hotspot develops stress in the busbar and the surrounding area in the form of cracks. In theory, busbars are made of copper-plated silver, and silver plating is necessary to improve current conductivity.

In this experiment, the material of the affected region of the busbar was obtained using the SEM image. According to the results shown in Fig. 11, it is recognised that the material (silicon) of the defective area of the cell is merged with silver, significantly reducing the busbar silver-plate composition, 60% silver, 37% silicon, and 2% other material. This arrangement in the solar cell is merely evidence of why the current is dropping in the non-shaded area of the cell, making this part of the cell affected by a significant increase in the temperature (hotspot).

Finally, two solar cells (Fig. 12) were tested for further validation of the above-mentioned results. Both samples are affected by mode 4, with severe breakdown regions. The inactive part is approximately higher than 70%, represented by the dark black areas in the EL image. Both samples were tested under STC conditions using the




Figure 10. Capturing the busbar under SEM of the solar cell affected by 60% shading ratio.




Figure 11. The busbar has 60% silver, 37% silicon, and 2% other material.

solar illuminator. Because the inactive region is very high, no increase in the cell's temperature was detected. This result confirms that when the solar cell is impacted by a high ratio of shading or breakdown regions, the hotspots are unlikely to develop.

Comparative study

To explain the significance and the new analysis presented in this study, our work has been compared, as shown in Table 1, with the most advanced recent research available in the literature^{13,25,26,29}. Our work is the only one which describes the correlation between four different crack modes and the development of hotspots. All other studies have mainly considered analysing one^{13,25} or two²⁶ crack modes. In contrast²⁹, investigated cracks and area defects in solar cells without remarking the difference between the variations in the cracks and their correlation with the output power losses and hotspots.

Furthermore, we have investigated the solar cell samples with different inspection techniques, including EL, thermal and SEM. On the contrary, there has not been previous research that used all three different inspection techniques to study the behaviour of cracks in solar cells.

Conclusions

This work reports on the correlation of solar cells cracks modes and their impact on the cell's temperature, well known as hotspots. For a solar cell affected by crack modes 1 or 2, there are no hotspots detected. However, we have discovered that the solar cell is likely to have hotspots if affected by crack mode 3 or 4, with an expected increase in the temperature from 25°C to 100°C. Additionally, we have noticed that an increase in the shading ratio in solar cells can cause severe hotspots. With this in mind, we observed that the worst-case scenario for




Figure 12. Solar cells affected by mode 4 with severe breakdown regions (a) sample #1, and (b) sample #2.

Reference/year of study	Investigated solar cell cracks	Inspection Method			Correlation between crack and hotspots
		EL	thermal	SEM	
¹³ /2019	Only cracks (0.5 cm) are studied	n/a	n/a	Included	n/a
²⁵ /2021	Only micro-cracks (5 and 10 μm) are investigated	n/a	Included	n/a	n/a
²⁶ /2021	Analysis based on nonuniform and uniform crack distributions	Included	n/a	Included	n/a
²⁹ /2021	Cracks, area defects, and finger interruptions	Included	n/a	n/a	n/a
This work/2021	Classified into four different modes: crack free, micro-crack, shade area, and breakdown	Included	Included	Included	Investigated for all crack modes

Table 1. Comparative study of this work with previously published papers^{13,25,26,29}.

the hotspot to develop is at shading ratios of 40% to 60%, with a foreseen increase in the cell temperature from 25°C to 105°C.

Data availability

The datasets generated and analysed during the current study are available from the corresponding author (M.D.) on reasonable request.

Received: 10 August 2021; Accepted: 24 November 2021

Published online: 14 December 2021

References

- Owen-Bellini, M. *et al.* Towards validation of combined-accelerated stress testing through failure analysis of polyamide-based photovoltaic backsheets. *Sci. Rep.* **11**(1), 1–13 (2021).
- Dhimish, M. Thermal impact on the performance ratio of photovoltaic systems: A case study of 8000 photovoltaic installations. *Case Stud. Therm. Eng.* **21**, 100693 (2020).
- Disney, C. E., Pillai, S. & Green, M. A. The Impact of parasitic loss on solar cells with plasmonic nano-textured rear reflectors. *Sci. Rep.* **7**(1), 1–10 (2017).
- Dhimish, M. & Badran, G. Photovoltaic hot-spots fault detection algorithm using fuzzy systems. *IEEE Trans. Device Mater. Reliab.* **19**(4), 671–679 (2019).
- Chen, H., Yi, H., Jiang, B., Zhang, K. & Chen, Z. Data-driven detection of hot spots in photovoltaic energy systems. *IEEE Trans. Syst. Man Cybern.: Syst.* **49**(8), 1731–1738 (2019).

6. Vásquez, P. *et al.* Inspection data collection tool for field testing of photovoltaic modules in the atacama desert. *Energies* **14**(9), 2409 (2021).
7. Dhimish, M., Mather, P. & Holmes, V. Evaluating power loss and performance ratio of hot-spotted photovoltaic modules. *IEEE Trans. Electron Devices* **65**(12), 5419–5427 (2018).
8. Kikelj, M., Lipovšek, B., Bokalič, M. & Topič, M. Spatially resolved electrical modelling of cracks and other inhomogeneities in crystalline silicon solar cells. *Prog. Photovoltaics Res. Appl.* **29**(1), 124–133 (2021).
9. Dhimish, M. Micro cracks distribution and power degradation of polycrystalline solar cells wafer: Observations constructed from the analysis of 4000 samples. *Renew. Energy* **145**, 466–477 (2020).
10. Chen, H., Zhao, H., Han, D. & Liu, K. Accurate and robust crack detection using steerable evidence filtering in electroluminescence images of solar cells. *Opt. Lasers Eng.* **118**, 22–33 (2019).
11. Paggi, M., Berardone, I., Infuso, A. & Corrado, M. Fatigue degradation and electric recovery in Silicon solar cells embedded in photovoltaic modules. *Sci. Rep.* **4**(1), 1–7 (2014).
12. Parikh, H. R. *et al.* Solar cell cracks and finger failure detection using statistical parameters of electroluminescence images and machine learning. *Appl. Sci.* **10**(24), 8834 (2020).
13. Wieghold, S. *et al.* Detection of sub-500- μm cracks in multicrystalline silicon wafer using edge-illuminated dark-field imaging to enable thin solar cell manufacturing. *Sol. Energy Mater. Sol. Cells* **196**, 70–77 (2019).
14. Dhimish, M., Holmes, V., Mehrdadi, B. & Dales, M. The impact of cracks on photovoltaic power performance. *J. Sci.: Adv. Mater. Devices* **2**(2), 199–209 (2017).
15. Silvestre, S., Boronat, A. & Chouder, A. Study of bypass diodes configuration on PV modules. *Appl. Energy* **86**(9), 1632–1640 (2009).
16. Vieira, R. G., de Araújo, F. M., Dhimish, M. & Guerra, M. I. A comprehensive review on bypass diode application on photovoltaic modules. *Energies* **13**(10), 2472 (2020).
17. Ghosh, S., Yadav, V. K. & Mukherjee, V. A novel hot spot mitigation circuit for improved reliability of PV module. *IEEE Trans. Device Mater. Reliab.* **20**(1), 191–198 (2020).
18. Dhimish, M., Holmes, V., Mather, P. & Sibley, M. Novel hot spot mitigation technique to enhance photovoltaic solar panels output power performance. *Sol. Energy Mater. Sol. Cells* **179**, 72–79 (2018).
19. d'Alessandro, V., Guerriero, P. & Daliento, S. A simple bipolar transistor-based bypass approach for photovoltaic modules. *IEEE J. Photovolt.* **4**(1), 405–413 (2013).
20. Dhimish, M., Holmes, V., Mehrdadi, B., Dales, M. & Mather, P. PV output power enhancement using two mitigation techniques for hot spots and partially shaded solar cells. *Electr. Power Syst. Res.* **158**, 15–25 (2018).
21. de Oliveira, M. C. C., Cardoso, A. S. A. D., Viana, M. M. & Lins, V. D. F. C. The causes and effects of degradation of encapsulant ethylene vinyl acetate copolymer (EVA) in crystalline silicon photovoltaic modules: A review. *Renew. Sustain. Energy Rev.* **81**, 2299–2317 (2018).
22. Miller, D. C., Owen-Bellini, M. & Hacke, P. L. Use of indentation to study the degradation of photovoltaic backsheets. *Solar Energy Mater. Solar Cells* **201**, 110082 (2019).
23. Chen, S. *et al.* Thorough subcells diagnosis in a multi-junction solar cell via absolute electroluminescence-efficiency measurements. *Sci. Rep.* **5**(1), 1–6 (2015).
24. Ji, W. *et al.* The work mechanism and sub-bandgap-voltage electroluminescence in inverted quantum dot light-emitting diodes. *Sci. Rep.* **4**(1), 1–7 (2014).
25. Mathusuthanan, M., Gembali, M., Narayanan, K. R. & Jayabal, K. Analysis of micro-cracks evolution in silicon cell during entire solar photovoltaic module manufacturing process. *Sol. Energy* **224**, 1160–1169 (2021).
26. Dhimish, M., d'Alessandro, V., & Daliento, S. Investigating the impact of cracks on solar cells performance: Analysis based on nonuniform and uniform crack distributions. *IEEE Transactions on Industrial Informatics*, early access (2021).
27. Akram, M. W. *et al.* Study of manufacturing and hotspot formation in cut cell and full cell PV modules. *Sol. Energy* **203**, 247–259 (2020).
28. Oh, W., Choi, H. & Kim, D. Analysis of the impact of power loss due to snail trails in a 95-kWp photovoltaic power system. *Microelectron. Reliabil.* **1**, 114230 (2021).
29. Rodriguez, A. *et al.* Automatic solar cell diagnosis and treatment. *J. Intell. Manuf.* **32**(4), 1163–1172 (2021).

Acknowledgements

This work was supported by the proof-of-concept (funding No. apr52020) fund by AL-MARRI Ltd, Doha, Qatar. In addition, M.D. would like to acknowledge the use of solar simulator and the scanning electron microscopy was supported by the University of Huddersfield, Huddersfield HD1 3DH, United Kingdom.

Author contributions

Both authors discussed the organization and the content of the manuscript. M.D. performed the experiments, prepared figures, and wrote the main manuscript text. P.I.L. validated the experimental results and revised the manuscript. Both authors have approved the manuscript before submission.

Competing interests

The authors declare no competing interests.

Additional information

Correspondence and requests for materials should be addressed to M.D.

Reprints and permissions information is available at www.nature.com/reprints.

Publisher's note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.



Open Access This article is licensed under a Creative Commons Attribution 4.0 International License, which permits use, sharing, adaptation, distribution and reproduction in any medium or format, as long as you give appropriate credit to the original author(s) and the source, provide a link to the Creative Commons licence, and indicate if changes were made. The images or other third party material in this article are included in the article's Creative Commons licence, unless indicated otherwise in a credit line to the material. If material is not included in the article's Creative Commons licence and your intended use is not permitted by statutory regulation or exceeds the permitted use, you will need to obtain permission directly from the copyright holder. To view a copy of this licence, visit <http://creativecommons.org/licenses/by/4.0/>.

© The Author(s) 2021